

**1 Products affected**

Product hierarchy no. *			Part no.	SBU	Type / Description	Customer part no.
SBU	PG	PGU	Type			
02	007	003	0000002293	4793.XXXX.XX	Connectors	4793
02	007	003	0000002294	4794.XXXX.XX	Connectors	4794

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

**2 Type of change**

Relocation of production

**3 Detailed description of change**

**SCHURTER**

(1P) Part No. **4793.3000**



(Q) Qty. **100**



Appliance inlet

4793

(1T) Lot No. 1234567



(9D) Date Code 1207



SE

(4L) CoO: **CZ**



Country of origin: CZ (for Czechia)

**SCHURTER**

(1P) Part No. **4793.3000**



(Q) Qty. **100**



Appliance inlet

4793

(1T) Lot No. 1234567



(9D) Date Code 1207



SE

(4L) CoO: **CN**



Country of origin: CN (for China)

**4 Reason of change**

Relocation of production

**5 Released date**

Release for series production

WW08/2012

**6 Impact of change and recommended action**

Form: N/A  
Fit: N/A  
Function: N/A  
Production Site: Relocated to China

**7 Reference Documents / Attachments**

Kind of document	Document number	Remarks
none		

<b>4793 / 4794</b>					<b>0118.2090</b>	
creation date	created by	release date	released by	notification no.	revision	page
2012-02-13	sha	2012-02-14	sha	23128		1 of 1