

**1 Products affected**

| Product hierarchy no. * |     |     |            | Part no.       | SBU                            | Type / Description | Customer part no. |
|-------------------------|-----|-----|------------|----------------|--------------------------------|--------------------|-------------------|
| SBU                     | PG  | PGU | Type       |                |                                |                    |                   |
| 02                      | 006 | 019 | 0000001800 | See list below | Power Entry Module with Filter | 5003               |                   |
|                         |     |     |            |                |                                |                    |                   |

\*SBU (2-digit) / PG (3-digit) / PGU (3-digit) / Type (10-digit)

| List of part numbers affected |             |             |             |             |
|-------------------------------|-------------|-------------|-------------|-------------|
| 5003.1111.1                   | 5003.1311.1 | 5003.2111.1 | 5003.2311.1 |             |
| 5003.1211.1                   | 5003.1411.1 | 5003.2211.1 | 5003.2411.1 |             |
|                               |             |             |             |             |
| 5003.1121.1                   | 5003.1221.1 | 5003.1321.1 | 5003.1323.1 | 5003.1421.1 |
|                               |             |             |             |             |
| 5003.115B.1                   | 5003.125B.1 | 5003.135B.1 | 5003.145B.1 |             |
| 5003.116B.1                   | 5003.126B.1 | 5003.136B.1 | 5003.146B.1 |             |


**2 Type of change**

Filter cases for front and rear mounting have a new surface treatment process.


**3 Detailed description of change**

Surface treatment process of filter case has changed with no change of surface material.

**Screw versions front-side**



**Screw versions rear-mounting**



| 5003          |            |              |             |                  | 0118.2248 |        |
|---------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date | created by | release date | released by | notification no. | revision  | page   |
| 2014-10-28    | buechpi    | 2015-04-13   | buechpi     | 26907            | -         | 1 of 2 |

#### 4 Reason of change

Improved production process.

#### 5 Release date

The change will be rolled-out starting ww 04/2015 and lasts approx. 12 months depending on the variant.

#### 6 Impact of change and recommended action

|                  |    |   |
|------------------|----|---|
| Form:            | No | No change to form but more shiny surface  |
| Fit:             | No | There are no dimensional changes          |
| Function:        | No | This is a non-functional change           |
| Production Site: | No | There is no change of the production site |
| Product Label:   | No | No change to product label                |
| Customer action  | No | Notification only                         |

#### 7 Reference Documents / Attachments

| Kind of document              | Document number | Remarks   |
|-------------------------------|-----------------|---|
| List of affected part numbers | -               | 5003_PCN_affected part numbers.xlsx   |
| Data sheet                    | 5003            | <a href="http://www.schurter.com/pdf/english/typ_5003.pdf">http://www.schurter.com/pdf/english/typ_5003.pdf</a> |

| 5003          |            |              |             |                  | 0118.2248 |        |
|---------------|------------|--------------|-------------|------------------|-----------|--------|
| creation date | created by | release date | released by | notification no. | revision  | page   |
| 2014-10-28    | buechpi    | 2015-04-13   | buechpi     | 26907            | -         | 2 of 2 |